Certificate of Compliance

 Certificate Number
 180604-BP181

 Report Reference
 BP181 - 19840921

Issue Date 2004 June 18



Issued to: Sargent & Greenleaf Inc.

1 Security Drive Nicholasville, KY 40356

This is to certify that representative samples of

Models 6280 Series

Models 6280-004,-005,-006,-008,-011,-012,-013,-014,-015,-016, two

movement 144 hr time locks.

Have been investigated by Underwriters Laboratories Inc.® in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety:

UL887 - Delayed Action Time Locks

Additional Information:

None

Only those products bearing the UL Listing Mark should be considered as being covered by UL's Listing and Follow-Up Service.

The UL Listing Mark generally includes the following elements: the symbol UL in a circle:

with the word "LISTED"; a control number (may be alphanumeric) assigned by UL; and the product category name (product identifier) as indicated in the appropriate UL Directory.

Look for the UL Listing Mark on the product

Issued by:
Debbie Schinleber Deffie John LO.

Underwriters Laboratories Inc.

Reviewed by:

Underwriters Laboratories Inc.